

NE 24th St at 172nd Ave NE Slope Stabilization
Question & Answers
Bid Number 20074

1/7/2021

Q01: We have been unable to find an architectural treatment pattern specified or depicted in the plans. Can you advise if a formliner architectural treatment pattern is required? If so, please furnish pattern details.

A01: An architectural treatment pattern is not required.