





All data are approximate and should be used for relative location reference only.
2013 Aerial Photograph (COB).



- Groundwater Elevation Contours
- ⬢ Monitoring Wells
- ⌵ Fenceline
- - - Sanitary Sewer Line

Prepared for:

City of
Bellingham




Prepared by:

nwhatcom
ENVIRONMENTAL


Groundwater Contour
Map (09/19/2017)

210 McKenzie
RI/FS
09/20/17

Figure G-23



All data are approximate and should be used for relative location reference only.
2013 Aerial Photograph (COB).



- Groundwater Elevation Contours
- ⬢ Monitoring Wells
- Fence Line
- - - Sanitary Sewer Line

Prepared for:




Prepared by:



Groundwater Contour
Map (09/20/2018)

210 McKenzie
RI/FS
10/01/18

Figure G-24



All data are approximate and should be used for relative location reference only.
2013 Aerial Photograph (COB).

0 20 40 60 80 100 120 140
Feet
1 inch = 70 feet

- Monitoring Wells
- Groundwater Elevation Contours
- Fence Line
- Sanitary Sewer Line

Prepared for:




Prepared by:




Groundwater Contour
Map (08/06/2019)

210 McKenzie
RI/FS
08/07/19

Figure G-25



All data are approximate and should be used for relative location reference only.
2013 Aerial Photograph (COB).



- ◆ Monitoring Wells
- Groundwater Elevation Contours
- x—x—x— Fenceline
- - - Sanitary Sewer Line

Prepared for:




Prepared by:



Groundwater Contour
Map (09/14/2020)


210 McKenzie
RI/FS
10/12/20

Figure G-26



- | | |
|---|----------------------|
| — Natural Gas Line | Sewer Manhole |
| — Fiber Optic Lines | Catch Basin |
| — Electrical Lines | Fenceline |
| — Sanitary Sewer Lines | Property Structures |
| — Water Lines | Topographic Contours |
| — Storm Sewer | Property Boundary |
| Impacted Areas (Soil) | Impermeable Surfaces |

All data are approximate and should be used for relative location reference only. 2020 aerial photograph (GoogleEarth).



Prepared for:



City of
Bellingham

Prepared by:



Site Map

210 McKenzie Avenue
Bellingham, WA 98225

210 McKenzie Ave

02/26/24

Figure A-3



1989 Soil Borings 1989 Test Pit 2007 Surface Soil Sample 2020 Test Pit Locations	2020 Soil Boring Locations - Existing Monitoring Well - Inaccessible Monitoring Well - Result Exceeded CUL - Result Met CUL	- Surface Remedial Excavations 2007 Test Trenches 2012 Test Pit Locations - Remaining Impacted Areas (Soil) - Fenceline	All data are approximate and should be used for relative location reference only. 2020 aerial photograph (GoogleEarth).	Prepared for:  City of Bellingham	Prepared by: 	0 25 50 75 Feet 1 inch = 50 feet	Historical Groundwater Sample Analytical Results Summary Map 210 McKenzie Avenue Bellingham, WA 98225
						210 McKenzie Ave 02/26/24	Figure A-6



- | | |
|---|---|
|  Remaining Impacted Areas (Soil) |  Historic Oil Tanks |
|  Surface Remedial Excavations |  Historic Structures |
|  Historic Remedial Excavation |  Fenceline |

All data are approximate and should be used for relative location reference only.
2020 aerial photograph (GoogleEarth).

Prepared for:
 City of Bellingham

Prepared by:


Interim Action Location Map

210 McKenzie Avenue Bellingham, WA 98225	
210 McKenzie Ave 02/26/24	Figure A-7